



*Oscillation causes the voltage measurement to be unstable, but average the listed voltage with "speed" and "intensity" controls at their max (full clock-wise) settings.

DPTD Foot Switch



MPSA18
NPN BJT



MODTM

www.modkitsdiy.com
Copyright © 2011 by modkitsdiy.com

"The Trill" (K-960) Schematic